



MAXgreen JOB COMPLETION FORM

Customer Name: Shannon Doram
 Address: 75 Seneca Rise N.W.
 Phone #: 403 700-4498
 Charity of Choice: _____

Project Completion Date: January 21'14
 Project Consultant: Garry Kornelsen
 Lead Installer: Alan Ma

Any outstanding issues to rectify? Entry door has a large scratch. Plygem to repair. NEW DOOR BEING DELIVERED SD

Please rate the following on a scale of 1 (poor) to 10 (excellent), or N/A if not applicable

Punctuality of the Consultant	<input type="text" value="10"/>	Friendliness of the Installers	<input type="text" value="10"/>
Responsiveness to Your Questions	<input type="text" value="10"/>	Cleanliness of the Installers	<input type="text" value="9"/>
Overall Experience with the Consultant	<input type="text" value="10"/>	Overall Installation Quality	<input type="text" value="10"/>
Overall Quality of the Windows/Doors	<input type="text" value="10"/>	Overall Experience with Installers	<input type="text" value="10"/>
Punctuality of the Installers	<input type="text" value="10"/>	Overall Satisfaction with MAXgreen	<input type="text" value="10"/>

Would you recommend MAXgreen to your friends and family? Yes / No
 May we share your comments / feedback with other potential customers? Yes / No
 May we use your name and phone number as a reference for other customers? Yes / No
 If no, may we use only your name and comments for testimonials? Yes / No / N/A

Comments / Feedback The service we experienced with Maxgreen was exceptional; right from the initial consultation through to job completion. The installation crew identified & helped us address some rotting we would have otherwise never uncovered & fixed it promptly. We would highly recommend MAXgreen to friends & family. In fact, we already have.
 (use back of page if more room is required).

Lead Installer:
[Signature]
 (Signature)
Alan Ma
 (Print Name)

Homeowner:
[Signature]
 (Signature)
Shannon Doram
 (Print Name)